

GE 230 - Check Sheet

M: 15041

Keys: 1- Ignition

VIN# 46121717904536

ODO (KM): 11292

Year: 1989

Condition: Fair condition

Rust: 6 of 10. Rust repair patches, 3 rust holes size 3/4"-1"

Emblems: Missing Hood, Mirror Emblems

Interior Trim: 8 of 10 Front, 7 of 10 Rear

Canvas Top: 8 of 10

Fuel Added:

\$11,500

Charging Test:

Voltage (battery/charging): 25.4/27.7

ELECTRICAL/LIGHTS:

Turn Signals

Reverse Lights

Dome - Does not work in position 2

Headlights Hi/Lo

Brake Light

License Plate Light - Wires cut

Running Lights

Dome

License Plate Light

Blower Motor

RUN TEST:

Transmission - All Gears

T-Case Lo

Transmission - No 1st gear manual

Transfer Case Hi

Rear Locker

Operating Temp Good

BRAKE TEST:

Normal

Needs Work

Comments: Rust center of w/shield exterior. Rt. Rear over tire rust thru. Left rear inner fender rust thru.

Definitely repairable, but will require cut out and weld in. Transmission likely linkage issue.

Equipment in Truck: TBD

Deficiencies:

Hood release intermittent-can't open. Tire carrier cracked. Dent LT RR Bumper

Inspector Mason