

**GE 230 - Check Sheet**

**M: 16092**

# Keys: 2-ignition

**Vin# 46121717906665**

**ODO: 36547**

**Year:**

Condition: Present and drives well

Rust: Passenger side windshield interior

Emblems: Has hood emblem, LT & RT mirror emblems missing

Interior Trim: 9/10 Front, 8/10 Rear normal wear

Canvas Top: 7/10 Front newer, 7/10 Older Rear, Window rear cracked LWR LT

Fuel Added:

**\$12,900**

Charging Test:

Voltage (battery/charging): 25.5/27.9

**ELECTRICAL/LIGHTS:**

Turn Signals

Reverse Lights

Headlights Hi/Lo

Brake Light

Running Lights

Dome

License Plate Light

Blower Motor

**RUN TEST:**

Transmission - All Gears

T-Case Lo

Transfer Case Hi

Rear Locker

Operating Temp Good

**BRAKE TEST:**

Normal

Needs Work

**Comments:**

Good cold start, overall nice truck only issue is the rust on windshield interior

passenger side. Tire Carrier NOT cracked.

**Equipment in Truck:**

Bulb kit, tool pouch, tire iron, bucket, brush, sponge, manual, manual pouch,

Shovel

**Deficiencies:**

Fuel pump always on with battery key. (Likely mis wired at relay)

Rust RH w/shield. Lower Passenger interior. Grill bent in slightly. RT headlight trim loose.

**Inspector** Mason