

GE 230 - Check Sheet

M: 16127

Keys: 1-Ignition, 1 padlock

Vin# 46121717906721

ODO: 14064

Year: 1991

Condition: Very nice with exception of door body damage.

Rust: Rt. Frt Fender, Lower rear corner

Emblems: Hood and Left mirror missing emblems

Interior Trim: 8/10

Canvas Top: 10/10 Front New, 7/10 Rear older, Window rust stain

Fuel Added:

\$12,000-\$12,500

DR Damage

Charging Test:

Voltage (battery/charging): 25.5/27.6

ELECTRICAL/LIGHTS:

Turn Signals

Reverse Lights

License Plate Late Rt - inop

Headlights Hi/Lo

Brake Light

Running Lights

Dome

License Plate Light

Blower Motor

RUN TEST:

Transmission - All Gears

T-Case Lo

Transfer Case Hi

Rear Locker

Operating Temp Good

BRAKE TEST:

Normal

Needs Work

Comments:

Good cold start, after fuel stumbles from stop, ran ruff then cleared up. Need

to redrive there was a wobble in steering on Courtula Parkway in the curves (check tire pressure), loow speed

exhaust or vibration. Undercarriage very clean.

Equipment in Truck:

Manul, manual pouch, tow strap, gease gun, fording kit, bucket

Deficiencies:

Dmaged RT Passenger Door, small damage to RT QTR related to door damage.

Hot start issues-long cranking migh be fuel related, dent RT RR wheelwell on rear upper edge

Rear tire carrier NOT cracked. Lt RR slider little damage. Cracked metal LH side tailgate

Inspector Mason

opening. Dent RH R Corner @ seem.