

GE 230 - Check Sheet

M: 16552

Keys: 2-Ignition, 1 padlock

Vin# 46121717907313

ODO: 78124

Year: 1991

Condition: Presents well, older top but good condition

Rust: Hood center RT surface, small bubbles RT RR QTR

Emblems: Hood , Left and Righ mirror emblems missing

Interior Trim: 9/10 Front, 8/10 Rear normal wear

Canvas Top: 8/10 Front, 8/10 Rear older windows round corners

Fuel Added:

\$13,900

Charging Test:

Voltage (battery/charging): 26.2/27.6

ELECTRICAL/LIGHTS:

Turn Signals

Reverse Lights

Headlights Hi/Lo

Brake Light

Running Lights

Dome

License Plate Light

Blower Motor

RUN TEST:

Transmission - All Gears

T-Case Lo

Transfer Case Hi

Rear Locker

Operating Temp Good

BRAKE TEST:

Normal

Needs Work

Comments:

Hard cold start, ruff idle, newer exhaust/cat

****Newer front axle can be outfitted with front locker.

Equipment in Truck:

Fording kit, bulb box, manual, manual pouch, bucket, brush, sponge, tool pouch,

grease gun

Deficiencies:

Spare tire mount cracked, not completely yet, not locking fuel cap, dent RR RR

upper QTR just below rear canvas, dent/whole interior passenger door, oil on valve conve - might be oil cap

Rt RR slider trim piece loose. Missing some symbols on air controls.

Inspector Mason